Field Note Record

Contract No.	Station	Mile/Line:	c/s					
				0/3	C/S			
009359	Section 1	I-90						
Staked by	Date	Work Started Date		Work Completed Date				
Survey		8/5/2019						
8/5/2019								
Calculated by	, Date	Checked by	Date	Inspector	Date			
Scott Busby		E. Knudson		Scott Busby	9/5/19			
9/5/2019		9/10/2019						

ITEM NO. 9 Section 1 - I-90, MP 33.44 to MP 136.43 AES. (weathered) TR. BEAM GUARDRAIL ANCHOR TYPE 1

Group Number 5

8/12/2019 - I-90

Station LE 634+79 to LE 634+86, MP 43.419 - RT - Install **One EA** AES TR Beam Guardrail Anchor Type 1

Notes: Type 1 Anchor includes two CRT Posts and 6'3" W-Beam How Measured: Per Each and Verified in the field

How Measured: Per Each and Verified in the field

Item Num	Material Brand Name/Model Type	Man	Manufacturer Trinity Highway Products, LLC Natina Superior Wood Treating				RAMS/QF Ref. No.	PL Appr//	Acc	Basis of Accept		
009.01	Beam Guardrail Anchors					QPL-0003			/	Manufacturer's Certificate of Compliance and Supporting Test Result		
009.03.03	Other Weathering Agent	Natir				RAM-0002		2 8	/	Submit Sample per Contract Special Provisions Lumber Grading Stam or Grading Certificate and Certificate of Treatment. (If Aquatic Envir. Std. Spec. 9-09 (1) Applies)		
009.04	Beam Guardrail Wood Pos and Blocks	Supe					QPL-0005		/			rtificate of Aquatic
Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.		sted By Date	ı	Checked By Init. Date		Est. No.
0009	AES. TR. BEAM GUARDRAIL ANCHOR TYPE 1	5	9/5/2019	EAC H	1	286	EK	09/11/19				6

Attachments



Things to do 82-2.xlsx Microsoft Excel Worksheet 409 KB

DOT Form IP 422-635ER EF Revised 4/2009